

# U.S. Senate

## Desk Description and Condition Report

Desk No : **66.00084.000**

Paper Label No.(on shelf bottom): 86

Painted No. (on bottom): N/A

Other identifying labels or marks (specify location): Stretcher: 86, 88, LXXXIV / Top: (stamped) 86, (pencil) 82/ Drawer Bottom: outside - (pencil) "McManard" ; inside - /Drawer Back: (pencil) No / Bottom of Shelf (other than paper label): / Drawer Blade: / Inside Case Back: (tape) "Metzenbaum"/ Inkwell: (tape) "McIntire"

### Description of Desk

Dimensions (in inches)

	Overall	Orig. Desk*	Case	Shelf
Height	34 7/8	32 1/4		
Width (front)	28 1/4	26 1/4	25 1/8	
Width (rear)	26 1/2	24 1/2	23 3/8	
Depth	20 1/4	20 1/8	19 1/8	9 1/2

\* Note: Dimensions do not include "booster" blocks added to feet or writing top.

### Woods

Primary: Mahogany ☒  
 Mahogany veneer ☒  
 Rosewood veneer ☒  
 Other Wood (specify): \_\_\_\_\_  
 \_\_\_\_\_

Character of case mahogany: Plain ☐  
 Ribbon ☐  
 Mottled ☐  
 Crotch ☐  
 Other ☐

Secondary:

Element	Pine	Ash	Poplar	Mahog	Other
Drawer Sides			✓		
Drawer Bottom			✓		
Drawer Back			✓		
Case Interior			✓		
Drawer Front	✓				

## Construction Details

Leg:

Wood Type	rosewood crossband	other crossband	no crossband
mahog. veneer	✓		
solid mahogany			
other: _____			

Foot construction: 1-part ☐  
 2-part ☒  
 5-part ☐  
 Other: \_\_\_\_\_

Double bead on edge of leg: Bead: Thick ☐  
 Thin ☒  
 Leg Thickness: 1 5/16"

Shape of cross-stretcher edges: Rounded ☒  
 Rectangular ☐

Spindle type:	Thick	Thin	Other
Number		111	

Joinery of lower drawer blade to case sides: single dovetail ☐  
 2 dovetails ☒  
 3 dovetails ☐  
 lap joint ☐  
 other: \_\_\_\_\_

Shelf molding applied: Yes ☐  
 No ☒

Cockbead width on bottom of drawer front: Narrow ☐  
 Full width ☒

Opening in original top for inkwell: Yes ☒  
 No ☐

Roundels: Single piece ("yo-yo" form) ☒  
 Applied boss ☐

Inset distance of single bead on desk back panel: Side: 1 1/4"  
 Top: 9/16"  
 Bottom: 9/16"

No. of Glue Blocks	Case	Stretch'r	Shelf
Original/Old			
New/Recent			2
Missing			

Interior case-side flush with corner block? Yes ☒  
 No ☐

Width of drawer-opening offset Right: 1/2"  
 Left: 1/2"

## Condition of Desk

### Structure

Previous breaks in structural elements: Yes ☒  
(shown on schematic)  
No ☐

Current split or broken elements: Yes ☐  
(shown on schematic)  
No ☒

Other loose or damaged joinery: Yes ☐  
(describe in narrative)  
No ☒

Damage to drawer front: Extreme ☐  
Moderate ☒  
Minor ☐

Drawer lock: relocated on face No ☒

Drawer lock: resized on inside Yes ☒

Cockbead on drawer front: Damaged ☒  
(show on schematic)  
Missing ☐  
Loose ☐  
Replacements ☒

Replaced drawer-side runners: Yes ☒  
No ☐

Replaced case-side runners: Yes ☒  
No ☐

Drawer bottom pieced-out at back edge: Yes ☒  
No ☐

Wear on Feet	Extreme	Moderate	Minor
Front	✓		
Rear			✓

Number of loose spindles: No: 0

Number of replaced spindles: (show on schematic) No: 0

Replaced veneers and cross-banding: Yes ☐  
(show on schematic)  
No ☒

Missing veneers and cross-banding: Yes ☒  
(show on schematic)  
No ☐

Delaminated/loose veneers & cross-banding: Yes ☐  
(show on schematic)  
No ☒

Shelf supports: Original/old ☐  
New/recent ☒  
Missing ☐

Spindle support board in case: Yes ☐  
No ☒

## Finish

Age	Excellent	Good	Fair	Poor
New			✓	
Old				
Unk.				

Note: Describe finish problems in narrative.

## Hardware/Attachments

Item	Mismatch	Missing	Damaged
Knob (L)			
Knob (R)			✓

Toe cap size:

Right toe: 16

Left toe: 16